

Attachment- A JCI Jones Photo Log 6/21/12 RMP/GDC Inspection

JCI0	Air Compressor
JCI1	Bleach Machine
JCI2	ER Gear
JCI3	50 % Sodium Hydroxide Tank
JCI4	Hypochlorite Solution Tanks 12.5%
JCI5	ER Shutoff
JCI6	Cylinder Room
JCI7	New/Reconditioned Valve Station
JCI8	Railcar Closure System
JCI9	ER Shutoff
JCI10	Detector railcar
JCI11	Railcar with loading rack
JCI12	Railcar with automatic shutoff